0K

Michael O. Leavitt Governor Robert L. Morgan Executive Director

Executive Director

Lowell P. Braxton

Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY www.nr.utah.gov

July 5, 2002

TO:

Internal File

THRU:

Daron R. Haddock, Permit Supervisor

FROM:

James D. Smith, Senior Reclamation Specialist

RE:

2001 First Quarter Water Monitoring, CO-OP Mining Company, Bear Canyon

Mine, C/015/025-WQ01-1

1. Were data submitted for all of the MRP required sites?

YES[X] NO[]

Identify sites not monitored and reason why, if known:

No access at BC-4, SBC-14, and SBC-17; No flow at BC-3 and SBC-6.

2. On what date does the MRP require a five-year resampling of baseline water data. See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling Due Date

Renewal submittal due 07/02/00, renewal due 11/02/00. Baseline parameters are to be taken in August of year 5 prior to each permit renewal (Table 7.1-8). Baseline parameters were measured August 2000 and included with the Third Quarter 2000 data submittal.

3. Were all required parameters reported for each site?

YES[]

NO [X]

Comments, including identity of monitoring site:

BC-2: total suspended solids not reported;



Page 2 C/015/025-WQ01-1 July 5, 2002

]	4. Were irregularities found in the data? Comments, including identity of monitoring site:	YES [X]		NO [
	SBC-3: cation – anion balance is greater than 5 percent; SBC-4: cation – anion balance is greater than 5 percent; SBC-5: cation – anion balance is greater than 5 percent; BC-1: cation – anion balance is greater than 5 percent; SBC-13: K (n = 21) is outside the two standard deviation	range;		
5.	Were DMR forms submitted for all required sites?			
		1 st month,	_	
		2 nd month,		
	Identify sites and months not monitored:	3 rd month,	YES [X]	NO[]
wa	Site 007, which is the not-yet-built sedimentation pond at as not active.	the Wild Ho	rse Ridge A	Addition,
6.	Were all required DMR parameters reported? Comments, including identity of monitoring site:	YES [X]	NO []
	No discharge from any UPDES points during the first qua	ırter		
7.	Were irregularities found in the DMR data? Comments, including identity of monitoring site:	YES[]	NO []	X]
	No discharge from any UPDES points during the first qua	arter		
8. Based on your review, what further actions, if any, do you recommend?				

O:\015025.BCN\WATER QUALITY\JDSWQ_01-1.DOC